

AC/DC Clamp Meter

MODEL: Prova CM-07

Features

- High Resolution
- DC 10mA, AC 1mA
- True RMS
- Non-contact Current Frequency Measurement
- 23mm Large Jaw Diameter
- One Touch Zero for DCA adjustment
- Large 3-3/4 Digits LCD (4000 counts)
- Fast Analog Bar-Graph Display
- Max/Min, Data Hold



#135-Prova-CM-07

Kit Includes:

Carrying Case, Instruction Manual,
Safety Test Leads, Battery

Specifications

Range	Resolution	Accuracy	Remarks
DCA 0-40A	10mA	1.0% ± 2 dgts	
DCA 0-150A	100mA	1.0% ± 2 dgts	
DCA 150-200A	100mA	2.2% ± 2 dgts	
DCA 200-400A	100mA	4.0% ± 4 dgts	50/60Hz
ACA 0-4A	1mA	1.5% ± 3 dgts	True RMS
ACA 0-40A	10mA	1.0% ± 3 dgts	True RMS
ACA 0-100A	100mA	1.0% ± 3 dgts	True RMS
ACA 100-200A	100mA	2.2% ± 3 dgts	True RMS
ACA 200-400A	100mA	4.0% ± 4 dgts	True RMS
Hz 0-1000KHz	0.1-1KHz	0.5% ± 2 dgts	0.1A sensitivity Autorange